

10/31/2001



	2001
X	PART NO.

AR12	X				
AR13		X			
ARX20			X		
ARX23				X	
BASIC PARTS	X				

900 Watts, 120 V., 60 Hz.

KEY #	DESCRIPTION	PART #	QUANTITY REQ'D				
			1	2	3	4	5
1	DUST LID-WHT	108430-000-000	1		1		
1	DUST LID-BLK	108430-006-000		1		1	
2	BREW BASKET ASSY.-WHT	108430-001-000	1		1		
2	BREW BASKET ASSY.-BLK	108430-007-000		1		1	
3	DECANTER LID	108430-003-000	1				
4	WARMING PLATE	108430-005-000	1				
5	HEATER ASSY.	108430-004-000	1				
6**	SWITCH ON/OFF	108430-002-000	1	1			
7	CONTROL MODULE	108430-008-000			1	1	
8	DECANTER	PD12ME	1		1		
8	DECANTER	PD13ME		1		1	
9	FEET	108430-009-000	2				
-	INST. BOOK	107607-000-000	1				

** NOT SHOWN IN DRAWING



Free Manuals Download Website

<http://myh66.com>

<http://usermanuals.us>

<http://www.somanuals.com>

<http://www.4manuals.cc>

<http://www.manual-lib.com>

<http://www.404manual.com>

<http://www.luxmanual.com>

<http://aubethermostatmanual.com>

Golf course search by state

<http://golfingnear.com>

Email search by domain

<http://emailbydomain.com>

Auto manuals search

<http://auto.somanuals.com>

TV manuals search

<http://tv.somanuals.com>